

Customer Comments For FUNKE(Changzhou) Products

Name of customer : Bosch Rexroth(Changzhou) Co., Ltd.
 Tel:Tel:+86 519 8175 000

Address: Changzhou , Jiangsu, China
 FK/QR8.2.1-01

The type of the heat exchanger: CP604-4-2P

Evaluate item	Content/Comments	Excellent	Very good	Good	Fair	Poor	Suggestions of discontented
Quality of Products	Package	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Exterior	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Performance	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
Service	Content of specification	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Timely	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Availability	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Attitude of servicer	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Technic of servicer	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
Price	Price of product	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Maintenance cost	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Transporation	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
Delivery	Timely	<input checked="" type="checkbox"/> Excellent	<input type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
	Availability	<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Very good	<input type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> poor	
About other suggestions and discontented:							

Please send to Funke Heat Exchanger Systems(Changzhou) Co., Ltd. when finished the table

Address: NO. 9, Longrui Road, Wujin HI-TECH INDUSTRIAL ZONE, 213164, Changzhou, Jiangsu, P. R. China
 Tel: +86 519 8867 1600 Fax: +86 519 8867 2081

Date: 21/06/2008